



## NATIONAL GUARD READINESS CENTER TEXAS MILITARY DEPARTMENT

### CLIENT

TEXAS MILITARY DEPARTMENT

### LOCATION

EL PASO, TEXAS

### ROLE

THIRD PARTY INSPECTION REVIEW

### PROJECT

\$5.7 MILLION

The Texas National Guard building in northeast El Paso, TX was renovated as part of the statewide Texas Armory Revitalization Program.

The improvements of the 40,000 square-foot facility included asbestos abatement, demolition of internal walls, new geothermal system, painting, flooring, plumbing, HVAC, fire protection system, and parking lot asphalt.

ECM provided construction inspections for all aspects of the construction including the electrical, mechanical, civil, and plumbing improvements and served as the third-party inspector for payment applications. Coordination, documentation, and reporting of inspections with the owner and contractor were some of the deliverables.